

# MAH County 2007 - 2015 Capital Improvement Program - Bridge Projects on the State System

8/1/2006

SFN	Fiscal Year	PID	County	RT	Route	R S	Begin SLM	S D	Feature Intersected	G A	F L	W S	P T	Treatment Category	Treatment Types	Main Structure Type	% Legal Load	Suff. Rating	Overall Structure Length	Deck Width	Deck Area	Year Built
5000157	2011	78300	MAH	SR	00007	*	7.75		CHARLES DITCH	6	2	2		Minor Rehabilitation	Substructure (other) (099)	111	125	085.6	14	81	1,130	1935
5003660	2008	25292	MAH	SR	00011	*	3.05		SR 11	6	3	2	7	Major Rehabilitation	Deck replacement (004)	322	145	079.0	283	35	9,795	1972
5000459	2008	19911	MAH	SR	00011	*	6.10		UNDER WESTERN RE	6	3	2	5	Major Rehabilitation	Painting str steel (020)	322	150	073.0	289	28	8,084	1972
5000459	2008	19911	MAH	SR	00011	*	6.10		UNDER WESTERN RE	6	3	2	5	Major Rehabilitation	Deck replacement (004)	322	150	073.0	289	28	8,084	1972
5000513	2011	76319	MAH	SR	00011	*	8.02	L	OVER RELOC INDIAN	6	3	2	6	New Construction	Structure widening (005)	322	150	096.2	213	44	9,375	1972
5000513	2011	76319	MAH	SR	00011	*	8.02	L	OVER RELOC INDIAN	6	3	2	6	Major Rehabilitation	Painting str steel (020)	322	150	096.2	213	44	9,375	1972
5000513	2011	76319	MAH	SR	00011	*	8.02	L	OVER RELOC INDIAN	6	3	2	6	Major Rehabilitation	Deck replacement (004)	322	150	096.2	213	44	9,375	1972
5000548	2011	76319	MAH	SR	00011	*	8.02	R	OVER RELOC INDIAN	6	3	2	6	New Construction	Structure widening (005)	322	150	096.2	213	44	9,375	1972
5000548	2011	76319	MAH	SR	00011	*	8.02	R	OVER RELOC INDIAN	6	3	2	6	Major Rehabilitation	Painting str steel (020)	322	150	096.2	213	44	9,375	1972
5000548	2011	76319	MAH	SR	00011	*	8.02	R	OVER RELOC INDIAN	6	3	2	6	Major Rehabilitation	Deck replacement (004)	322	150	096.2	213	44	9,375	1972
5000572	2007	25288	MAH	SR	00011	*	10.11	L	US62 (SHIELDS RD.)	6	1	2		Reactive Maintenance	Conc patch(non-deck) (010)	112	150	088.6	119	44	5,231	1970
5000572	2007	25288	MAH	SR	00011	*	10.11	L	US62 (SHIELDS RD.)	6	1	2		Preventive Maintenance	Deck patching (concrete) (04)	112	150	088.6	119	44	5,231	1970
5000572	2007	25288	MAH	SR	00011	*	10.11	L	US62 (SHIELDS RD.)	6	1	2		Preventive Maintenance	Deck overlay(other) (044)	112	150	088.6	119	44	5,231	1970
5000602	2007	25288	MAH	SR	00011	*	10.11	R	US62 (SHIELDS RD)	6	1	2		Reactive Maintenance	Conc patch(non-deck) (010)	112	150	088.6	119	44	5,231	1970
5000602	2007	25288	MAH	SR	00011	*	10.11	R	US62 (SHIELDS RD)	6	1	2		Preventive Maintenance	Deck patching (concrete) (04)	112	150	088.6	119	44	5,231	1970
5000602	2007	25288	MAH	SR	00011	*	10.11	R	US62 (SHIELDS RD)	6	1	2		Preventive Maintenance	Deck overlay(other) (044)	112	150	088.6	119	44	5,231	1970
5000637	2008	19911	MAH	SR	00011	*	11.99		KIRK RD	6	2	2	8	Major Rehabilitation	Deck replacement (004)	322	150	091.2	281	40	11,238	1970
5000661	2008	19911	MAH	SR	00011	*	13.02		NEW RD (CR162)	6	3	2	8	Major Rehabilitation	Deck replacement (004)	322	150	092.8	306	40	12,239	1970
5000696	2007	25288	MAH	SR	00011	*	13.42		OAKCREST DRIVE	7	2	2	8	Preventive Maintenance	Bridge railing upgrade/repair (	322	150	079.5	283	34	9,623	1968
5000718	2008	19911	MAH	SR	00011	*	14.12		MAHONING AVE (CR 18	6	3	2	8	New Construction	Structure widening (005)	322	150	087.8	282	65	18,331	1970
5000718	2008	19911	MAH	SR	00011	*	14.12		MAHONING AVE (CR 18	6	3	2	8	Major Rehabilitation	Deck replacement (004)	322	150	087.8	282	65	18,331	1970
5000718	2008	19911	MAH	SR	00011	*	14.12		MAHONING AVE (CR 18	6	3	2	8	Preventive Maintenance	Spot painting structural steel	322	150	087.8	282	65	18,331	1970
5000726	2007	25288	MAH	SR	00011	*	14.55	L	OVER NORQUEST BLV	6	1	2		Reactive Maintenance	Conc patch(non-deck) (010)	112	150	095.5	132	44	5,802	1970
5000726	2007	25288	MAH	SR	00011	*	14.55	L	OVER NORQUEST BLV	6	1	2		Preventive Maintenance	Deck patching (concrete) (04)	112	150	095.5	132	44	5,802	1970
5000726	2007	25288	MAH	SR	00011	*	14.55	L	OVER NORQUEST BLV	6	1	2		Preventive Maintenance	Deck overlay(other) (044)	112	150	095.5	132	44	5,802	1970
5000750	2007	25288	MAH	SR	00011	*	14.55	R	OVER NORQUEST BLV	6	1	1		Reactive Maintenance	Conc patch(non-deck) (010)	112	150	096.5	132	44	5,802	1970
5000750	2007	25288	MAH	SR	00011	*	14.55	R	OVER NORQUEST BLV	6	1	1		Preventive Maintenance	Deck patching (concrete) (04)	112	150	096.5	132	44	5,802	1970
5000750	2007	25288	MAH	SR	00011	*	14.55	R	OVER NORQUEST BLV	6	1	1		Preventive Maintenance	Deck overlay(other) (044)	112	150	096.5	132	44	5,802	1970
5000750	2007	25288	MAH	SR	00011	*	14.55	R	OVER NORQUEST BLV	6	1	1		Preventive Maintenance	Deck overlay(other) (044)	112	150	096.5	132	44	5,802	1970
5000785	2007	25288	MAH	SR	00011	*	15.34		LANTERMAN ROAD (T	6	2	2	6	Reactive Maintenance	Conc patch(non-deck) (010)	322	150	091.0	290	37	10,592	1970
5006309	2010	76328	MAH	SR	00011	*	16.01	R	EB 680 OVER SR 11 NB	7	2	2	8	Minor Rehabilitation	Substructure (other) (099)	322	150	087.3	193	44	8,493	1967
5001048	2011	77855	MAH	SR	00014	*	0.35		ISLAND CREEK	8	1	1		Reactive Maintenance	Deck overlay(asp w waterpr	231	150	091.9	67	36	2,411	1991
5001064	2011	77855	MAH	SR	00014	*	1.99		W.BRANCH OF MILL C	7	2	2		Reactive Maintenance	Deck overlay(asp w waterpr	231	150	079.7	12	27	323	1997
5001072	2011	77855	MAH	SR	00014	*	4.60		GARFIELD DITCH	9	1	1		Minor Rehabilitation	Substructure (other) (099)	111	150	099.5	30	44	1,324	1997
5001072	2011	77855	MAH	SR	00014	*	4.60		GARFIELD DITCH	9	1	1		Preventive Maintenance	Channel clean out (087)	111	150	099.5	30	44	1,324	1997
5001080	2011	77855	MAH	SR	00014	*	7.16		UNDER NORFOLK SOU	5	3		2	Minor Rehabilitation	Substructure (other) (099)	321	0	N/A	46	64	2,928	1930
5001145	2011	77855	MAH	SR	00014	*	8.95		MIDDL FK LITTLE BEAV	5	3	2	4	Minor Rehabilitation	Substructure (other) (099)	322	150	081.5	133	44	5,856	1955
5001145	2007	23704	MAH	SR	00014	*	8.95		MIDDL FK LITTLE BEAV	5	3	2	4	Major Rehabilitation	Painting str steel (020)	322	150	081.5	133	44	5,856	1955
5001145	2007	23704	MAH	SR	00014	*	8.95		MIDDL FK LITTLE BEAV	5	3	2	4	Major Rehabilitation	Deck replacement (004)	322	150	081.5	133	44	5,856	1955
5001242	2011	77855	MAH	SR	00014	*	9.23		OVER MID FK LITTLE B	6				Minor Rehabilitation	Culvert (other) (139)	395	150	092.0	14	0	388	1974
5001242	2011	77855	MAH	SR	00014	*	9.23		OVER MID FK LITTLE B	6				Preventive Maintenance	Channel clean out (087)	395	150	092.0	14	0	388	1974
5001277	2011	77855	MAH	SR	00014	*	9.53		LITTLE BEAVER CREE	7				Minor Rehabilitation	Culvert (other) (139)	195	150	097.5	16	0	549	1998
5001277	2011	77855	MAH	SR	00014	*	9.53		LITTLE BEAVER CREE	7				Preventive Maintenance	Channel clean out (087)	195	150	097.5	16	0	549	1998
5001471	2007	19281	MAH	SR	00045	*	2.63		LITTLE BEAVER CREE	4	3	1		New Construction	Structure(repl) (002)	122	150	042.1	86	27	2,303	1928
5003067	2015	77878	MAH	SR	00045	*	12.32	L	OVER MAH 45 1200 L	6	2	2		Minor Rehabilitation	Substructure (other) (099)	112	150	093.7	164	42	6,889	1968
5003091	2015	77878	MAH	SR	00045	*	12.32	R	OVER MAH 45 1200 R	6	2	2		Minor Rehabilitation	Substructure (other) (099)	112	150	093.7	164	42	6,889	1968
5007143	2009	25508	MAH	US	00062	*	0.00		OVER US62DA-F & SR7	6	2	1	6	Major Rehabilitation	Painting str steel (020)	322	150	090.6	211	88	18,568	1963
5007143	2009	25508	MAH	US	00062	*	0.00		OVER US62DA-F & SR7	6	2	1	6	Major Rehabilitation	Deck replacement (004)	322	150	090.6	211	88	18,568	1963
5008522	2007	23752	MAH	US	00062	D	0.10	L	SOUTH AVENUE CR15	6	4	2	7	Major Rehabilitation	Deck replacement (004)	322	150	096.0	144	51	7,276	1971
5008514	2007	23752	MAH	US	00062	D	0.10	R	SOUTH AVENUE CR15	6	3	2	7	Major Rehabilitation	Deck replacement (004)	322	150	090.9	142	52	7,427	1971
5005434	2007	25279	MAH	US	00062	T	0.27		SR-7, FUTURE USR-62	6	2	2	7	Minor Rehabilitation	Substructure (other) (099)	322	150	088.0	203	86	17,459	1969
5001838	2008	76320	MAH	US	00062	*	2.07		MID FK LITTLE BEAVER	4	3	2		New Construction	Structure(repl) (002)	121	150	043.4	54	33	1,765	1931
5000572	2007	25288	MAH	US	00062	*	10.75	L	US62 (SHIELDS RD.)	6	1	2		Reactive Maintenance	Conc patch(non-deck) (010)	112	150	088.6	119	44	5,231	1970
5000572	2007	25288	MAH	US	00062	*	10.75	L	US62 (SHIELDS RD.)	6	1	2		Preventive Maintenance	Deck patching (concrete) (04)	112	150	088.6	119	44	5,231	1970
5000572	2007	25288	MAH	US	00062	*	10.75	L	US62 (SHIELDS RD.)	6	1	2		Preventive Maintenance	Deck overlay(other) (044)	112	150	088.6	119	44	5,231	1970
5000602	2007	25288	MAH	US	00062	*	10.75	R	US62 (SHIELDS RD)	6	1	2		Reactive Maintenance	Conc patch(non-deck) (010)	112	150	088.6	119	44	5,231	1970
5000602	2007	25288	MAH	US	00062	*	10.75	R	US62 (SHIELDS RD)	6	1	2		Preventive Maintenance	Deck patching (concrete) (04)	112	150	088.6	119	44	5,231	1970
5000602	2007	25288	MAH	US	00062	*	10.75	R	US62 (SHIELDS RD)	6	1	2		Preventive Maintenance	Deck overlay(other) (044)	112	150	088.6	119	44	5,231	1970
5001935	2010	77856	MAH	US	00062	*	12.75		ANDERSON RUN	6	1	1		Minor Rehabilitation	Culvert (other) (139)	231	150	086.3	37	34	1,259	1990
5007208	2009	25508	MAH	US	00062	*	17.51		OVER I680	5	3	2	4	Major Rehabilitation	Painting str steel (020)	322	150	077.0	205	58	11,873	1963
5007208	2009	25508	MAH	US	00062	*	17.51		OVER I680	5	3	2	4	Major Rehabilitation	Deck replacement (004)	322	150	077.0	205	58	11,873	1963
5007208	2012	81594	MAH	US	00062	*	17.51		OVER I680	5	3	2	4	Minor Rehabilitation	Substructure (other) (099)	322	150	077.0	205	58	11,873	1963
5008662	2008	24073	MAH	US	00062	*	18.23		SR289 MAHONING R S	5	2	2	3	Major Rehabilitation	Painting str steel (020)	322	150					

# MAH County 2007 - 2015 Capital Improvement Program - Bridge Projects on the State System

8/1/2006

SFN	Fiscal Year	PID	County	RT	Route	R S	Begin SLM	S D	Feature Intersected	G A	F L	W S	P T	Treatment Category	Treatment Types	Main Structure Type	% Legal Load	Suff. Rating	Overall Structure Length	Deck Width	Deck Area	Year Built
5004446	2010	25235	MAH	SR	00193	*	0.52		SERVICE ROAD	5	2	1		Minor Rehabilitation	Substructure (other) (099)	112	150	074.8	119	101	12,013	1966
5004470	2010	25235	MAH	SR	00193	*	0.72		CONRAIL & RAYEN AV	5	3	2	5	Major Rehabilitation	Painting str steel (020)	322	150	075.4	789	101	79,675	1967
5004470	2010	25235	MAH	SR	00193	*	0.72		CONRAIL & RAYEN AV	5	3	2	5	Major Rehabilitation	Deck replacement (004)	322	150	075.4	789	101	79,675	1967
5005132	2010	25235	MAH	SR	00193	*	0.99	R	US422 W FEDERAL ST	6	2	2	7	Major Rehabilitation	Deck replacement (004)	322	150	090.1	199	90	17,911	1967
5005132	2010	25235	MAH	SR	00193	*	0.99	R	US422 W FEDERAL ST	6	2	2	7	Major Rehabilitation	Painting str steel (020)	322	150	090.1	199	90	17,911	1967
5004500	2010	25235	MAH	SR	00193	*	1.05	R	SR 193 NB UNDER CO	6	2	2	6	Reactive Maintenance	Conc patch(non-deck) (010)	322	150	088.8	156	90	14,036	1967
5004500	2010	25235	MAH	SR	00193	*	1.05	R	SR 193 NB UNDER CO	6	2	2	6	Reactive Maintenance	Conc patch(non-deck) (010)	322	150	088.8	156	90	14,036	1967
5004500	2010	25235	MAH	SR	00193	*	1.05	R	SR 193 NB UNDER CO	6	2	2	6	Preventive Maintenance	Slope repair & protection inst	322	150	088.8	156	90	14,036	1967
5004500	2010	25235	MAH	SR	00193	*	1.05	R	SR 193 NB UNDER CO	6	2	2	6	Preventive Maintenance	Slope repair & protection inst	322	150	088.8	156	90	14,036	1967
5004500	2010	25235	MAH	SR	00193	*	1.05	R	SR 193 NB UNDER CO	6	2	2	6	Preventive Maintenance	Deck patching (concrete) (04)	322	150	088.8	156	90	14,036	1967
5004500	2010	25235	MAH	SR	00193	*	1.05	R	SR 193 NB UNDER CO	6	2	2	6	Preventive Maintenance	Deck patching (concrete) (04)	322	150	088.8	156	90	14,036	1967
5004500	2010	25235	MAH	SR	00193	*	1.05	R	SR 193 NB UNDER CO	6	2	2	6	Preventive Maintenance	Drainage system cleaned/rep	322	150	088.8	156	90	14,036	1967
5004500	2010	25235	MAH	SR	00193	*	1.05	R	SR 193 NB UNDER CO	6	2	2	6	Preventive Maintenance	Drainage system cleaned/rep	322	150	088.8	156	90	14,036	1967
5004659	2007	23700	MAH	US	00224	*	6.21		BR TURKEY BROTH C	3	2	1		New Construction	Structure(repl) (002)	111	100	022.6	16	32	517	1900
5004772	2008	76443	MAH	US	00224	*	15.35		INDIAN RUN	6	2	1		New Construction	Structure(repl) (002)	111	130	085.4	20	80	1,604	1961
5004837	2009	25506	MAH	US	00224	*	16.19		OVER MILL CREEK	4	3	2		Major Rehabilitation	Deck replacement (004)	112	150	055.0	93	80	7,438	1961
5004837	2009	25506	MAH	US	00224	*	16.19		OVER MILL CREEK	4	3	2		Minor Rehabilitation	Superstructure (other) (039)	112	150	055.0	93	80	7,438	1961
5004853	2011	79864	MAH	US	00224	*	19.69		OVER I680	6	2	2	8	Major Rehabilitation	Deck replacement (004)	322	150	080.4	304	78	23,713	1974
5008662	2008	24073	MAH	SR	00289	*	2.30		SR289 MAHONING R S	5	2	2	3	Major Rehabilitation	Painting str steel (020)	322	150	069.0	2,113	78	164,808	1973
5008662	2008	24073	MAH	SR	00289	*	2.30		SR289 MAHONING R S	5	2	2	3	Major Rehabilitation	Deck replacement (004)	322	150	069.0	2,113	78	164,808	1973
5008662	2008	24073	MAH	SR	00289	*	2.30		SR289 MAHONING R S	5	2	2	3	Preventive Maintenance	Pin and Hanger retrofit (024)	322	150	069.0	2,113	78	164,808	1973
5004985	2008	25062	MAH	SR	00289	*	4.84		OVER TRIB MAHONING	4	3	2		Major Rehabilitation	Deck replacement (004)	111	150	054.0	18	84	1,507	1931
5005132	2010	25235	MAH	US	00422	*	1.85	R	US422 W FEDERAL ST	6	2	2	7	Major Rehabilitation	Deck replacement (004)	322	150	090.1	199	90	17,911	1967
5005132	2010	25235	MAH	US	00422	*	1.85	R	US422 W FEDERAL ST	6	2	2	7	Major Rehabilitation	Painting str steel (020)	322	150	090.1	199	90	17,911	1967
5005523	2010	77871	MAH	US	00422	*	7.80		OVER DRY RUN	4	3	1		New Construction	Structure(repl) (002)	121	105	051.3	33	59	1,927	1925
5005639	2008	25507	MAH	SR	00534	*	1.74		OVER GARFIELD DITC	6	2	2		Minor Rehabilitation	Substructure (other) (099)	111	150	099.8	23	42	969	1978
5006007	2009	76326	MAH	SR	00616	*	5.87		DRY RUN	4	3	2		New Construction	Structure(repl) (002)	112	150	057.8	75	52	3,929	1962
5006058	2009	76326	MAH	SR	00616	*	6.61		TRIBUTARY OF MCKEL	8	1	2		Reactive Maintenance	Deck overlay(asph w waterpr	171	150	098.0	18	34	614	1993
5006309	2010	76328	MAH	IR	00680	*	0.07	R	EB 680 OVER SR 11 NB	7	2	2	8	Minor Rehabilitation	Substructure (other) (099)	322	150	087.3	193	44	8,493	1967
5006279	2010	76328	MAH	IR	00680	*	0.20	L	OVER I80 EB SR 11NB	7	1	2	9	Minor Rehabilitation	Substructure (other) (099)	322	150	087.7	297	56	16,630	1965
5006333	2010	76328	MAH	IR	00680	*	0.33	L	WATER MAIN R/W (MV	6	2	2	9	Minor Rehabilitation	Substructure (other) (099)	322	150	091.4	229	42	9,623	1967
5006368	2010	76328	MAH	IR	00680	*	0.40	R	WATER MAIN R/W (MV	7	1	1	9	Minor Rehabilitation	Substructure (other) (099)	322	150	091.4	218	51	11,152	1967
5006392	2010	76328	MAH	IR	00680	*	0.67		FOUR MILE RUN RD	6	2	2	7	Minor Rehabilitation	Substructure (other) (099)	322	150	072.8	300	35	10,495	1967
5006422	2010	76328	MAH	IR	00680	*	1.23		LANTERMAN RD	7	2	2	8	Minor Rehabilitation	Substructure (other) (099)	322	150	074.6	341	33	11,248	1967
5006422	2010	76328	MAH	IR	00680	*	1.23		LANTERMAN RD	7	2	2	8	Preventive Maintenance	Deck overlay(concrete) (040)	322	150	074.6	341	33	11,248	1967
5006457	2010	76328	MAH	IR	00680	*	2.06	L	OVER MERIDIAN RD	6	2	2		Minor Rehabilitation	Substructure (other) (099)	112	150	074.4	148	52	7,696	1967
5006457	2010	76328	MAH	IR	00680	*	2.06	L	OVER MERIDIAN RD	6	2	2		Reactive Maintenance	Deck overlay(asph w waterpr	112	150	074.4	148	52	7,696	1967
5006481	2010	76328	MAH	IR	00680	*	2.06	R	OVER MERIDIAN RD	6	2	2		Minor Rehabilitation	Substructure (other) (099)	112	150	075.0	148	44	6,512	1967
5006481	2010	76328	MAH	IR	00680	*	2.06	R	OVER MERIDIAN RD	6	2	2		Preventive Maintenance	Deck overlay(concrete) (040)	112	150	075.0	148	44	6,512	1967
5006511	2010	76328	MAH	IR	00680	*	2.83		VESTAL RD	6	3	2	8	Minor Rehabilitation	Substructure (other) (099)	322	150	075.3	328	52	17,061	1967
5006511	2010	76328	MAH	IR	00680	*	2.83		VESTAL RD	6	3	2	8	Reactive Maintenance	Deck overlay(asph w waterpr	322	150	075.3	328	52	17,061	1967
5006570	2010	76328	MAH	IR	00680	*	3.15		PED WALK (ELBEREN	8	3		9	Major Rehabilitation	Deck replacement (004)	322	0	N/A	342	10	3,423	1969
5006570	2010	76328	MAH	IR	00680	*	3.15		PED WALK (ELBEREN	8	3		9	Minor Rehabilitation	Substructure (other) (099)	322	0	N/A	342	10	3,423	1969
5006600	2010	76328	MAH	IR	00680	*	3.32	L	OVER CHERRY HILL	6	2	2	5	Minor Rehabilitation	Substructure (other) (099)	322	150	094.0	135	44	5,942	1967
5006600	2010	76328	MAH	IR	00680	*	3.32	L	OVER CHERRY HILL	6	2	2	5	Reactive Maintenance	Deck overlay(asph w waterpr	322	150	094.0	135	44	5,942	1967
5006600	2010	76328	MAH	IR	00680	*	3.32	L	OVER CHERRY HILL	6	2	2	5	Preventive Maintenance	Painting structural steel (020)	322	150	094.0	135	44	5,942	1967
5006635	2010	76328	MAH	IR	00680	*	3.32	R	OVER CHERRY HILL	6	2	2	5	Minor Rehabilitation	Substructure (other) (099)	322	150	094.0	125	44	5,500	1967
5006635	2010	76328	MAH	IR	00680	*	3.32	R	OVER CHERRY HILL	6	2	2	5	Reactive Maintenance	Deck overlay(asph w waterpr	322	150	094.0	125	44	5,500	1967
5006635	2010	76328	MAH	IR	00680	*	3.32	R	OVER CHERRY HILL	6	2	2	5	Preventive Maintenance	Painting structural steel (020)	322	150	094.0	125	44	5,500	1967
5006694	2010	76328	MAH	IR	00680	*	3.42	L	OVER ERIE RR	6	2	2	5	Minor Rehabilitation	Substructure (other) (099)	322	150	089.9	187	56	10,473	1967
5006694	2010	76328	MAH	IR	00680	*	3.42	L	OVER ERIE RR	6	2	2	5	Reactive Maintenance	Deck overlay(asph w waterpr	322	150	089.9	187	56	10,473	1967
5006694	2010	76328	MAH	IR	00680	*	3.42	L	OVER ERIE RR	6	2	2	5	Preventive Maintenance	Painting structural steel (020)	322	150	089.9	187	56	10,473	1967
5006724	2010	76328	MAH	IR	00680	*	3.42	R	OVER ERIE RR	6	2	2	5	Minor Rehabilitation	Substructure (other) (099)	322	150	087.9	187	52	9,720	1967
5006724	2010	76328	MAH	IR	00680	*	3.42	R	OVER ERIE RR	6	2	2	5	Reactive Maintenance	Deck overlay(asph w waterpr	322	150	087.9	187	52	9,720	1967
5006724	2010	76328	MAH	IR	00680	*	3.42	R	OVER ERIE RR	6	2	2	5	Preventive Maintenance	Painting structural steel (020)	322	150	087.9	187	52	9,720	1967
5006759	2010	76328	MAH	IR	00680	*	3.74		BELLE VISTA AVENUE	6	2	2	9	Minor Rehabilitation	Substructure (other) (099)	322	150	072.8	194	44	8,536	1967
5006759	2010	76328	MAH	IR	00680	*	3.74		BELLE VISTA AVENUE	6	2	2	9	Reactive Maintenance	Deck overlay(asph w waterpr	322	150	072.8	194	44	8,536	1967
5006783	2010	76328	MAH	IR	00680	*	3.85		WELLINGTON ST	6	3	2	9	Minor Rehabilitation	Substructure (other) (099)	322	150	063.3	269	39	10,495	1967
5006783	2007	23765	MAH	IR	00680	*	3.85		WELLINGTON ST	6	3	2	9	Major Rehabilitation	Deck replacement (004)	322	150	063.3	269	39	10,495	1967
5006783	2007	23765	MAH	IR	00680	*	3.85		WELLINGTON ST	6	3	2	9	Preventive Maintenance	Spot painting structural steel	322	150	063.3	269	39	10,495	1967
5006848	2009	25508	MAH	IR	00680	*	4.29		RMP(SILLIMAN ST TO E	5	3	1	6	Major Rehabilitation	Deck replacement (004)	322	150	090.9	260	30	7,912	1963
5006848	2009	25508	MAH	IR	00680	*	4.29		RMP(SILLIMAN ST TO E	5	3	1	6	Major Rehabilitation	Deck replacement (004)	322	150	090.9	260	30	7,912	1963
5006848	2009	25508	MAH	IR	00680	*	4.29		RMP(SILLIMAN ST TO E	5	3	1	6	Major Rehabilitation	Painting str steel (020)	322						

# MAH County 2007 - 2015 Capital Improvement Program - Bridge Projects on the State System

8/1/2006

SFN	Fiscal Year	PID	County	RT	Route	R S	Begin SLM	S D	Feature Intersected	G A	F L	W S	P T	Treatment Category	Treatment Types	Main Structure Type	% Legal Load	Suff. Rating	Overall Structure Length	Deck Width	Deck Area	Year Built
5003253	2009	76321	MAH	IR	00680	*	14.37		OVER I 680	6	2	2	8	Preventive Maintenance	Deck overlay(concrete) (040)	322	150	087.0	294	65	19,106	1974
5007860	2013	23905	MAH	IR	00680	*	15.41	L	IR680 OVER CALLA RO	8	1	1	8	Minor Rehabilitation	Substructure (other) (099)	322	150	097.5	125	45	5,640	1975
5007879	2013	23905	MAH	IR	00680	*	15.41	R	IR680 OVER CALLA RO	8	1	1	8	Minor Rehabilitation	Substructure (other) (099)	322	150	097.5	126	45	5,662	1975
5003229	2009	76321	MAH	IR	00680	*	16.32		OVER I 680	6	2	3	8	Preventive Maintenance	Deck overlay(concrete) (040)	322	150	059.3	307	48	14,736	1974